Table of Contents

EXECUTIVE SUMMARY iii

CONCLUSIONS iv
RECOMMENDATIONS iv

SECTION 1: AVIATION RULEMAKING ADVISORY COMMITTEE TASKING 1

SECTION 2: GENERAL AVIATION MAINTENANCE WORKING GROUP 2

MEMBERSHIP LIST 2

SECTION 3: ANALYSIS OF THE GA MAINTENANCE WORKING GROUP'S GENERAL RECOMMENDATIONS 3

ORGANIZATIONAL CHANGES 3
MAJOR REPAIRS AND MAJOR ALTERATIONS 3
100-HOUR INSPECTION 4
TESTING ALTIMETERS AND TRANSPONDERS 4
REPAIR STATION DOCUMENTATION 5

SECTION 4: THE WORKING GROUP'S SPECIFIC RECOMMENDATIONS 6

APPENDIX 1: RECOMMENDED RULE LANGUAGE ..... APPENDIX 1–1

APPENDIX 2: DRAFT AC 43–203 ..... APPENDIX 2–1

APPENDIX 3: AIP DOCUMENT (AS DELIVERED TO ARAC ON DECEMBER 14, 1998) ..... APPENDIX 3–1